# ROSS ENVIRONMENTAL ASSOCIATES, INC.

Hydrogeology, Water Quality,
Contaminant Fate & Transport, Remediation,
& Regulatory Compliance and Permitting

SEP 2 0 2002



19 September 2002

Mr. Chuck Schwer
Department of Environmental Conservation
Waste Management Division
103 South Main Street, West Building
Waterbury, Vermont 05671-0404

RE: Initial Site Investigation Report Frank Adams School – St. Johnshury, Vermont

#### Dear Chuck:

Enclosed is one bound copy of the final report for the Initial Site Investigation completed at the Frank Adams School located in St. Johnsbury, Vermont.

Please feel free to call me, if you have any questions regarding the enclosed information or recommendations.

Sincerely,

Robert J. Ross, CGWP Principal Hydrogeologist

enclosure

cc. Mr. David Baker Mr. Edward Zuccaro - Zuccaro, Willis & Bent

Rjr/ref: 22040Cl01b

SEP 202002

Hydrogeology, Water Quality,
Contaminant Fate & Transport, Remediation,
& Regulatory Compliance and Permitting



# **Initial Site Investigation Report**

Frank R. Adams School Summer Street St. Johnsbury, Vermont

**SMS Site #: WMD 1195** 

22 August 2002

Prepared For:
David Baker
257 Weston Ave
Suite 2
St. Johnsbury Vermont 05819-0097

Phone: (802) 748-8616

## Prepared By:

Patricia Coppolino Ross Environmental Associates, Inc. P.O. Box 1533 Stowe, Vermont 05672

> Phone: (802) 253-4280 Fax: (802) 253-4829

R.E.A. Project No. 22-040 R.E.A. Document #: 22040ISI

# TABLE OF CONTENTS

|        |   | Page |
|--------|---|------|
| Exec   | utive Summary   | i    |
| Site I | Profile   | ii   |
| 1.0    | Introduction  |      |
|        | 1.1 Site Location and Setting                         |      |
|        | 1.2 Site History                                      | _    |
|        | 1.3 Land Use and Adjacent Property Ownership          |      |
| • •    |   |      |
| 2.0    | Field Investigation Results and Procedures            | 3    |
|        | 2.1 Contaminants of Concern                           | 3    |
|        | 2.2 Source Area Evaluation                            | 3    |
| •      | 2.3 Soil Boring and Monitoring Well Installation      | 3    |
|        | 2.4 Ground-Water Elevations and Flow Direction        | 4    |
|        | 2.5 Ground-Water Sampling and Analysis                | 5    |
|        | 2.6 Investigation Procedures                          | 7    |
| 3.0    | Sensitive Receptor Identification and Risk Assessment | 8    |
|        | 2.1 December 14 (28 of                                |      |
|        | 3.1 Receptor Identification                           | 8    |
|        | 5.2 Risk Assessment                                   | ð    |
| 4.0    | Data Evaluation and Regulatory Status                 | 9    |
| 5.0    | Recommendations                                       | 0    |
| . A    |   |      |
| 6.0    | References  | 0    |
|        |   |      |
|        | List of Appendices                                    |      |
|        |   |      |
|        | Appendix A Figures and Tables                         |      |
|        | Annondia B. Sito Dhotogwaho                           |      |
|        | Appendix B Site Photographs                           |      |
|        | Appendix C Soil Boring/Monitoring Well Logs           |      |
|        | Appendix D Laboratory Reports                         |      |
|        | Obberrow n runnium Mehates                            |      |

Ross Environmental Associates, Inc. (R.E.A.) has conducted an initial site investigation (ISI) at the Frank R. Adams School owned by the St. Johnsbury School District, located at 481 Summer Street in St. Johnsbury, Vermont. Field investigation included: installation of four soil borings/monitoring wells; field screening of subsurface soil samples for the possible presence of volatile organic compounds (VOCs); sampling and analysis of water from the four monitoring wells; and a receptor survey to identify potential risks to the environment and human health.

Available information indicates that groundwater beneath the School property has been impacted by fuel oil related compounds. The contamination present at the site is most likely from the former 6,500 gallon heating oil underground storage tank (UST) that was removed from the property in June 2002. At this time, subsurface petroleum contamination is located in the immediate vicinity of the former UST; however, the downgradient extent of dissolved phase contamination has not been defined.

On the basis of the results of this investigation and the conclusions stated above, *R.E.A.* makes the following recommendations.

- Additional soil borings/monitoring wells should be installed in the downgradient of the former UST to define the downgradient extent of contamination and to ensure that adjacent properties are not impacted by contaminant migration;
- Following the completion of the supplemental subsurface investigation, ground water samples should be collected and analyzed for the possible presence of volatile organic compounds (VOCs) and total petroleum hydrocarbons (TPH) by U.S. EPA Methods 8021B and 8015DRO, respectively; and
- A summary report should be completed following the completion of the additional work at the site, which will include recommendations for site remediation and/or long-term monitoring as appropriate.

Site Information

Site Name:

Frank R. Adams School

SMS Site #:

WMD 1195

Site Address:

481 Summer Street, St. Johnsbury, VT

Mailing Address:

257 Weston Ave, St. Johnsbury, VT

Telephone:

(802) 748-8616

Contact/Owner:

David Baker

Coordinates:

latitude 44° 25' 20.5" N, and longitude 72° 01' 16.5" W

Contaminants of Concern:

Fuel Oil

Source:

Suspected release from former UST system, UST system was removed on

20 June 2002.

**Aquifer Characteristics** 

Soil Type:

The soils at the site consisted primarily of medium sand.

Effective Porosity:

-0.3

Hydraulic conductivity:

0.25 to 14 ft/day

Ground-water flow direction:

North (7/10/02)

Horizontal hydraulic gradient:

5.0 (7/10/02)

Average ground water velocity:

4.1 to 233 ft/day

Ground-water depth bgs:

5.49 to 6.70 feet (7/10/02)

Saturated thickness:

>7 feet

Depth to Bedrock:

> 13 feet

Receptors

Drinking water:

The site and adjacent properties are served by municipal sewer and water

systems.

Ground water:

Impacted by petroleum contamination; see Table 2, Appendix A.

Surface water:

There are no surface water bodies within a close proximity to the site.

**Buildings:** 

The School is a one-story building constructed on an at-grade-slab

foundation.

Underground

utilities:

Water, sewer and storm drains are located along Winter Street, which is

located upgradient of the former UST.

Air Quality:

Possible fugitive emissions to the atmosphere may occur due to subsurface contamination. The possibility of ambient air contamination is very low,

but the risk would increase if subsurface soils were exposed.

## 1.0 INTRODUCTION

**R.E.A.** was retained by Mr. David Baker to complete an initial site investigation (ISI) at the Frank R. Adams School located on Summer Street in St. Johnsbury, Vermont in accordance with Vermont Department of Environmental Conservation (VT DEC) guidelines. The site investigation was initiated following the discovery of subsurface petrolcum contamination during the removal of a 6,500-gallon fuel oil UST on 20 June 2002. This report has been prepared by **R.E.A.** under the direction of Mr. David Baker; unauthorized use or reproduction of this report is prohibited, without written authorization from **R.E.A.**, or Mr. David Baker.

## 1.1 Site Location and Setting

The subject property, which is currently owned by the St. Johnsbury School District, is a former elementary school located in a residential area of St. Johnsbury, Vermont. The property is occupied by a single story brick building. The property is located on the corner of Summer and Winter Streets (Figure 1, Appendix A). The Site and surrounding properties are serviced by municipal sewer and water systems.

The ground surface has an average elevation of approximately 650 feet above mean sea level (Maptech, 1997). The geographic coordinates of the site are: latitude 44° 25' 20.5" N, and longitude 72° 01' 16.5" W.

The surficial geology in the vicinity of the site is mapped as littoral sediment, predominantly sand, well-sorted sand with no pebbles or boulders (Stewart and MacClintock, 1970). Bedrock in the St. Johnsbury area is mapped as the Waits River formation (Doll, 1961).

Figure 2 in Appendix A, shows the approximate locations of various site features. Photographs of the site and surrounding area taken in August 2002 are included in Appendix B.

#### 1.2 Site History

Prior to 1957, the property was used as a playground associated with the adjacent Summer Street School. In 1957, the school was constructed on the property. The former UST was installed in 1957 during the construction of the school.

On 20 June 2002 R.E.A. provided oversight of the removal of the fuel oil UST. The UST was found to be in poor condition, with some rust and pitting observed along the bottom center seam of the UST. Strong petroleum odors were noted directly beneath the tank, with petroleum contamination

extending into the underlying groundwater formation, which was encountered approximately ten feet bgs. Approximately 1/8-inch of free product was observed in the bottom of the UST excavation. PID readings on the soils in the excavation ranged from 12.2 to 347 parts per million volume (ppmv). Approximately 38 cubic yards of petroleum-contaminated soil was transported off site to ESMI for thermal destruction.

# 1.3 Land Use and Adjacent Property Ownership

The Frank Adams School is located in a residential area within the City limits of St. Johnsbury. The property is located on the corner of Summer and Winter Streets, which form the western and northern property boundaries, respectively. Private residences bound the eastern and southern boundaries of the school property.

# 2.0 FIELD INVESTIGATION RESULTS AND PROCEDURES

**R.E.A.**'s field investigation included: the installation of four soil borings/monitoring wells (MW-1, MW-2, MW-3, and MW-4); field screening of subsurface soil samples for the possible presence of VOCs; collection and analysis of water samples from four on-site monitoring wells; and a receptor survey to identify potential risks to the environment and human health. Approximate monitoring well locations and significant site features are shown on Figure 2 in Appendix A.

The objectives of this initial site investigation were to:

- Evaluate the degree and extent of petroleum contamination in soil and ground water;
- > Qualitatively assess the risks to the environment and public health via relevant sensitive receptors and potential contaminant migration pathways; and
- > Identify the need for further site characterization, appropriate monitoring, and/or remedial actions based on the site conditions.

## 2.1 Contaminants of Concern

Based on available information, the contaminants of concern (COC) at the site appear to include: benzene, toluene, ethylbenzene, xylene, 1,3,5-trimethyl benzene, 1,2,4-trimethyl benzene, and naphthalene. All of these contaminants are typically associated with fuel oil related petroleum products.

## 2.2 Source Area Evaluation

Current information suggests that the former heating oil UST system is the likely source of petroleum contamination discovered at the Site. During removal of the former UST, the tank was noted to be in poor condition, with some rusting and pitting. Free-product was observed in the bottom of the excavation after the removal of the UST.

# 2.3 Soil Boring and Monitoring Well Installation

On 3 July 2002, *R.E.A.* provided oversight during the installation of four soil borings/monitoring wells; MW-1 was installed in the vicinity of the former UST, MW-2 was installed in the apparent downgradient direction of the former UST, MW-3 and MW-4 were installed in crossgradient locations from the former UST. The soils at the site consisted primarily of well-sorted medium sand. The borings extended at least five feet below the water table, which was encountered between six and eight feet below ground surface (bgs) at the time of drilling. Soil borings for MW-1, MW-3 and MW-4 were all extended to approximately fifteen feet bgs. The soil boring for MW-2 was extended to approximately thirteen feet bgs.

Monitoring wells were constructed using 2-inch-diameter schedule 40 polyvinyl chloride (PVC), with flush-threaded joints. Seven foot sections of factory-slotted well screens (0.01-inch) were installed at the bottom of the borings; solid PVC risers extending to ground surface were used to complete each well. A clean sand pack was placed around the screened section of each monitoring well extending one to two feet above the top of the screen, with a bentonite seal placed above the sand pack. Flush-mounted road-box protective casings were installed over each monitoring well. Each well was developed after installation by hand bailing and removing eight to ten standing volumes of water. Soil descriptions and monitoring well construction details are included on the soil boring logs in Appendix B. Technical Drilling Services (TDS) of Sterling, Massachusetts installed the soil borings and monitoring wells using hollow stem auger drilling methods under direct supervision of *R.E.A.* 

After installation of the monitoring wells, R.E.A. surveyed the locations of the new monitoring wells in relation to existing site features and roadways. Each well was located in azimuth to an accuracy of  $\pm 1.0$  feet, and in elevation with an accuracy of  $\pm 0.01$  feet relative to an on-site benchmark of 100.00 feet for the top of casing at MW-2.

PID readings on soil samples collected during soil borings/monitoring wells installation from MW-1, MW-2 and MW-3 ranged from 0.0 to 312 ppmv. PID readings from MW-4 were 0.0 ppmv. PID

screening results are included on the soil boring logs in Appendix B. *R.E.A.*'s hydrogeologist screened soil samples from each soil boring for the possible presence of volatile organic compounds (VOCs) using a PE PhotoVac model 2020 portable PID. The PID was calibrated with an isobutylene standard gas to a benzene reference.

# 2.4 Ground Water Elevations and Flow Direction

On 10 July 2002, ground-water flow in the unconfined surficial aquifer at the site was generally toward the north, with an estimated hydraulic gradient of approximately five (5.0) percent (MW-3 to MW-2). Water-level measurements and elevation calculations for 10 July 2002 are presented in Table 1 and the ground-water contour map prepared using this data is presented as Figure 3, Appendix A.

No indications of free-phase petroleum were observed in any of the monitoring wells; however, petroleum odors and sheening were noted in monitoring wells MW-1 and MW-2 during purging and sample collection. Static water-table elevations were computed for each monitoring well by subtracting the corrected or measured depth-to-water readings from the surveyed top-of-casing (TOC) elevations, which are relative to an arbitrary site datum of 100.00 feet (MW-2).

The effective porosity of the medium sand encountered below the water-table is presumably around 0.3, with hydraulic conductivities ranging between 0.25 and 14 feet per day (Freeze & Cherry, 1979). Assuming Darcian flow, these estimates combine with the calculated horizontal gradient of five percent to yield an estimated range of ground-water flow velocities of between 4.1 and 233 feet per day. Contaminant migration would be less accounting for retardation and dispersion of the contaminants.

# 2.5 Ground-Water Sampling and Analysis

Available information indicates that the subsurface petroleum contamination discovered at the site, is characteristic of fuel oil. Contaminant distribution indicates the likely source of petroleum contamination on the school property is the former fuel oil UST, which was removed in June 2002. The downgradient extent of subsurface petroleum contamination has not been determined.

The Vermont Groundwater Enforcement Standards (VGESs) <sup>1</sup> for 1,3,5-trimethylbenzene, 1,2,4-trimethylbenzene, and naphthalene were exceeded in the ground water samples collected from monitoring wells MW-1, and MW-2. The highest total volatile petroleum compound concentration was detected in the sample collected from MW-2 (located downgradient of the former UST). Low concentrations of toluene and total xylenes were also detected in the sample collected from MW-1, and total xylenes were also detected in the MW-2 sample. No volatile petroleum compounds were detected in the samples collected from MW-3 or MW-4.

Total petroleum hydrocarbons (TPH) were detected in the samples collected from MW-1, MW-2, and MW-3 at concentrations between 0.66 and 9.09 milligrams per liter (mg/L). TPH was not detected above the detection limit of mg/L (MW-4) in samples collected on 10 July 2002.

No petroleum compounds were detected in the trip-blank sample. Analytical results for the blind field duplicate, collected from MW-2 (labeled MW-22), ranged from 0.0 percent to 7.2 percent for individual compounds; which is well below the EPA recommended percent difference of 30 percent. Greater than ten unidentified peaks (UIP's) were detected in samples collected from all four monitoring wells. The UIP's indicate that compounds other than those targeted for the 8021b analysis may be present in the groundwater at the Site.

Groundwater analytical results are summarized on Table 2, and copies of the laboratory analytical reports are included as Appendix C. Contaminant distribution based on water samples collected on 10 July 2002 is shown on Figure 4 in Appendix A. All of the samples were analyzed for the possible presence of volatile petroleum compounds and total petroleum hydrocarbons (TPH) in accordance with U.S. EPA Methods 8021B and 8015 for diesel range organics (DRO), respectively. All samples were transported under chain-of-custody in an ice-filled cooler to Endyne, Inc. of Williston, Vermont for laboratory analysis.

Immediately after sample collection, field measurements were obtained for pH, specific conductivity, temperature, total dissolved solids (TDS), and oxygen reduction potential (ORP). Review of field indicator parameters indicate that the ORP concentration was a little low indicating that anaerobic degradation of the contaminants may be occurring. A summary of the field measurement data is included on Table 3, in Appendix A.

<sup>&</sup>lt;sup>1</sup>The Vermont DEC has established groundwater enforcement standards for eight petroleum related VOCs, as follows: benzene - 5 ug/L; toluene - 1,000 ug/L; ethylbenzene - 700 ug/L; xylenes - 10,000 ug/L; MTBE - 40 ug/L; 1,3,5-trimethyl benzene - 4 ug/L; 1,2,4-trimethyl benzene - 5 ug/L; and naphthalene - 20 ug/L.

# 2.6 Investigation Procedures

The procedures used during the initial site investigation the former Burkewitz Oil Company are consistent with the following guidance documents:

- "Site Investigation Guidance." Vermont Agency of Natural Resources, Waste Management Division. August 1996.
- > "Corrective Action Guidance." Vermont Agency of Natural Resources, Waste Management Division, November 1997.
- "Agency Guidelines for Petroleum Contaminated Soil and Debris." Vermont Agency of Natural Resources, Waste Management Division. August 1996.
- > ASTM D 2488-93. "Standard Practice for Description and Identification of Soils (Visual-Manual Procedure)." American Society for Testing and Materials.
- > ASTM D 5092-90. "Standard Practice for Design and Installation of Ground Water Monitoring Wells in Aquifers." American Society for Testing and Materials.
- > ASTM D 4750-87. "Standard Test Method for Determining Subsurface Liquid Levels in a Borehole or Monitoring Well." American Society for Testing and Materials.
- > ASTM D 4448-85a. "Standard Guide for Sampling Ground Water Monitoring Wells." American Society for Testing and Materials.

# 3.0 SENSITIVE RECEPTOR IDENTIFICATION AND RISK ASSESSMENT

No sensitive receptors were identified immediately adjacent to the school property during the ISI; however, ambient air could be impacted if the subsurface soils in the area of the former UST were to be disturbed.

# 3.1 Receptor Identification

No receptors were identified.

## 3.2 Risk Assessment

On the basis of the information obtained during this investigation, *R.E.A.* has qualitatively assessed the risks that the subsurface contamination poses to human health and the environment. The findings are summarized as follows:

- > Exposure to contaminated media is possible during subsurface invasive activities. Personnel involved in these activities should be properly trained.
- > The school building is constructed on an at-grade-slab foundation.
- > No surface water bodies are located within close proximity of the site.

# 4.0 DATA EVALUATION AND REGULATORY STATUS

Available information indicates that groundwater beneath the site has been impacted by petroleum related compounds, which are characteristic of fuel oil. Contaminant distribution indicates the likely source of contamination at the site is the former heating oil UST. At this time, the downgradient extent of subsurface petroleum contamination has not been determined.

Generally, the VT DEC requires active remediation when greater than an 1/8" of free-product is present, or when human health or a sensitive receptor is impacted or threatened by contamination. Based on available information, active remediation at the site is not likely to be required. The VT DEC may require periodic monitoring of ground water beneath the site; however the frequency of future sampling events should be determined after confirmation of the initial results.

A summary of the significant findings of the ISI is outlined below:

- ➤ The Vermont Ground Water Enforcement Standards (VGESs) for 1,3,5-trimethylbenzene, 1,2,4-trimethylbenzene, and naphthalene were exceeded in the ground water samples collected from MW-1 and MW-2.
- No VOCs were detected in the samples collected from MW-3 and MW-4;
- Total petroleum hydrocarbons (TPH) were detected in the samples collected from MW-1, MW-2, and MW-3 at concentrations between 0.66 and 9.09 milligrams per liter (mg/L).
- ➢ PID readings on subsurface soil samples collected during soil boring for MW-1and MW-2, located directly adjacent to the former UST, ranged between 0.3 and 312 ppmv.
- PID readings on subsurface soil samples collected from the soil boring for MW-3, located cross-gradient from the former UST, ranged from 3.9 to 43.8 ppmv, and PID readings on subsurface soil samples collected from the MW-4 soil boring, located upgradient of the former UST were all 0.0 ppmv.
- > Ground water flow in the shallow overburden formation appears to flow to the north.
- No sensitive receptors were identified immediately adjacent to the school property during the ISI; however, ambient air could be impacted if the subsurface soils in the area of the former UST were to be disturbed.

## 5.0 RECOMMENDATIONS

On the basis of the results of this investigation and the conclusions stated above, R.E.A. makes the following recommendations.

- Additional soil borings/monitoring wells should be installed in the downgradient of the former UST to define the downgradient extent of contamination and to ensure that adjacent properties are not impacted by contaminant migration;
- Following the completion of the supplemental subsurface investigation, ground water samples should be collected and analyzed for the possible presence of VOCs and TPH by U.S. EPA Methods 8021B and 8015DRO, respectively; and
- A summary report should be completed following the completion of the additional work at the Site, which will include recommendations for site remediation and/or long-term monitoring as appropriate.

#### 6.0 REFERENCES

Doll, C.G. and others, 1961. "Geologic Map of Vermont", Office of the State Geologist.

Freeze. R. A., and Cherry, J.A., 1976. *Groundwater*, Prentice-Hall, Inc., Englewood Cliffs, New Jersey, 29 p.


Fetter, C.W., 1994. Applied Hydrogeology, 3rd Ed., Prentice Hall, Englewood Cliffs, New Jersey, 691 p.

Stewart, D.P. and MacClintock, P., 1970. "Surficial Geologic Map of Vermont", Office of the State Geologist.

Maptech, 1997. Orleans Quadrangle, Vermont. U.S. Geological Survey. 7.5 minute series (topographic). Provisional Edition, 1986. Maptech, Inc. Greenland, NH. 1997.

P
P
FIGURES AND TABLES

N
D
I
X



Source: USGS 1983. St. Johnsbury, VT. Provisional Edition 1983. Topographic map (7.5 X 15 minute series) Maptech, Inc. 1998. R.F. A. Project No. 22 044.

R.E.A. Project No. 22-044

Figure 1
Site Location Map
Frank Adams School
St. Johnsbury, Vermont

# SUMMER STREET North Tallonmental Asso FORMER TZU, Legend SITE PLAN - Monitoring Well Location (with monitoring well locations) Frank Adams School ---- Water/Sewer Line St. Johnsbury, Vermont

Ross Environmental Associates, Inc.

Stowe, Vermont (802) 253-4280

FIGURE 2

All locations are approximate

1"=40"-0"

ile Name

22-040

JULY 3 2002


Approved By

Drawn By

#### SUMMER STREET







TRC - Top of Casing Elevation GWE - Urbund Water Elevation Elevations relative to an arbitrary site datum of 100.00 feet.

#### Legend

Aug. Monitoring Well Location

---- Ground Water Contour

# GROUND WATER CONTOUR MAP

(Monitoring Date: 10 July 2002)
Frank Adams School
St. Johnsbury, Vermont

| •       | Drawn By |
|---------|----------|
| =40°-0° | TFMD     |
| Nome    | ed By    |
|         |          |


Ross Environmental Associates, Inc. Stowe, Vermont (802) 253-4280

FIGURE 3

#### SUMMER STREET







VDD: + Total valatile organic compounds, reported in ug/l.
TPH - Total petroleum hydrocarbons, reported in mg/t.
ND - Not detected during lab analysis.

#### Legend

———— Water/Sewer Line All locations are approximate CONTAMINANT DISTRIBUTION MAP

(Monitoring Date: 10 July 2002)

Frank Adams School St. Johnsbury, Vermont

| Scale     | Date   |        | Drawn By |
|-----------|--------|--------|----------|
| 1"=40'-0" | JULY S | 2002   | TPMD     |
| File Name |        | Арргом | ed By    |
| 22-040    |        |        |          |

Ross Environmental Associates, Inc. Stowe, Vermont (802) 253-4280

FIGURE 4

# TABLE 1 GROUND WATER ELEVATION CALCULATIONS

Frank Adams School St. Johnsbury, Vermont

Monitoring Date: 10 July 2002

| Well I,D. | Top of Casing<br>Elevation (ft) | Depth to Water<br>(feet, TOC) | Depth to<br>Bottom (BTOC) | Water Table<br>Elevation (ft) |
|-----------|---------------------------------|-------------------------------|---------------------------|-------------------------------|
| MW-1      | 99.76                           | 5.98                          | 13.01                     | 93.78                         |
| MW-2      | 100.00                          | 6.70                          | 12.05                     | 93.30                         |
| MW-3      | 99.79                           | 5.49                          | 13.16                     | 94.30                         |
| MW-4      | 99.53                           | 5.59                          | 12.50                     | 93.94                         |

All values reported in feet relative to arbitrary site datum of 100.00 feet

# TABLE 2 GROUND-WATER ANALYTICAL RESULTS

Frank Adams School Summer Street St. Johnsbury, Vermont

Monitoring Date: 10 July 2002

| Sample ID | MTBE    | Benzene | Toluene | Ethyl<br>benzene | Total<br>Xylenes | 1,3,5 TMB | 1,2,4 TMB | Napthalene | Total<br>VOCs | UIP | ТРН     |
|-----------|---------|---------|---------|------------------|------------------|-----------|-----------|------------|---------------|-----|---------|
| MW-1      | ND<10.0 | ND<5.0  | 10,9    | ND<5.0           | 46.7             | 17.4      | 30.6      | 35,5       | 141.1         | >10 | 7.63    |
| MW-2      | ND<10,0 | ND<5.0  | ND<5.0  | ND<5.0           | 14.7             | 16.6      | 48.8      | 124        | 204.1         | >10 | 9.09    |
| MW-3      | ND<2.0  | ND<1.0  | ND<1.0  | ND<1.0           | ND<2.0           | ND<1.0    | ND<1.0    | ND<1.0     | ND ND         | >10 | 0.66    |
| MW-4      | ND<2.0  | ND<1.0  | ND<1.0  | ND<1.0           | ND<2.0           | ND<1.0    | ND<1.0    | ND<1.0     | ND            | 0   | ND<0.40 |
| VGES      | 40      | 5.0     | 1,000   | 700              | 10,000           | 4.0       | 5.0       | 20         |               |     | 10.0.40 |

| Sample ID                         | MTBE    | Benzene | Toluene | Ethyl<br>benzene | Total<br>Xylenes | 1,3,5 TMB | 1,2,4 TMB | Napthalene | Total<br>VOCs      | UIP   | ТРН          |
|-----------------------------------|---------|---------|---------|------------------|------------------|-----------|-----------|------------|--------------------|-------|--------------|
| MW-2                              | ND<10,0 | ND<5.0  | ND<5.0  | ND<5.0           | 14.7             | 16.6      | 48.8      | 124        | 204.1              | >10   | D 00         |
| duplicate MW-2<br>(labeled MW-22) | ND<10.0 | ND<5.0  | ND<5.0  | ND<5.0           | 15.3             | 17.8      | 52,3      | 124        | 209.4              | >10   | 9.09<br>8.54 |
| % Difference                      | 0.0     | Ω.0     | 0.0     | 0.0              | 4.1              | 7.2       | 7.2       | 0.0        | 186 <b>n.e</b> 888 |       | _            |
| Trip Blank                        | ND<2.0  | ND<1.0  | ND<1.0  | ND<1.0           | ND<2.0           | ND<1.0    | ND<1.0    | ND<1.0     | 2,6<br>ND          | <br>0 | 6.1<br>NS    |

UIP: Unidentified Peaks.

Shaded values indicate exceedance of Vermont Groundwater Enforcement Standards (VGESs).

1,3,5-TMB: 1,3,5-trimethylbenzene 1,2,4-TMB: 1,2,4-trimethylbenzene

ND - None Detected NS - Not Sampled

# TABLE 3 FIELD MEASUREMENT DATA

Frank Adams School St. Johnsbury, Vermont

Monitoring Date: 10 July 2002

| Ql lleW | pH (su) | temperature<br>(°C) | Specific conductivity ( <i>u</i> .S) | ORP (mV) | TDS (ppm) |
|---------|---------|---------------------|--------------------------------------|----------|-----------|
| MW-1    | 5.90    | 15,1                | 830.5                                | 0        | 558.3     |
| MW-2    | 6.06    | 15.3                | 992.9                                | 0        | 673.2     |
| MW-3    | 6.69    | 15.2                | 899.9                                | 0        | 608.2     |
| MW-4    | 6.80    | 15.1                | 744.2                                | 0        | 499.3     |

pH reported in standard units (s.u.).

Specific conductivity reported in microsiemens (uS) or millisiemens (mS).

Oxidation-reduction potential (ORP) reported in millivolts (mV).

Total dissolved solids (TDS) reported in parts per million (ppm) or parts per (ppt) thousand.

A
P
P
P
E
SITE PHOTOGRAPHS

N
D
I
X

B

A
P
P
P
SOIL BORING
MONITORING WELL LOGS
N
I
X

C

|   |      | S.E  | .⊲(.      |   |                             | BORING /                             | WELL ID  | ENT               | ΊFΙ            | CATION: M                 | W-1           |                    |  |
|---|------|--|-----------|---|-----------------------------|--------------------------------------|--|-------------------|----------------|---------------------------|---------------|--------------------|--|
|   | S.   |  |           | Ų.  |                             |                                      | SITE NAME:   | Fran              | k Ac           | dams School               |               |                    |  |
|   | 84 w | Control of the Contro |           | <u></u>   |                             |                                      | STIR LOCATION:   |                   |                | bury, Vermont             |               |                    |  |
|   | 62   | a Maketa   |           | Ž.  |                             | INST/                                | ILLATION DATE:   | 2 Jul             |                |                           | -             |                    |  |
|   |      | "" on warial   | 18. F 18. |   |                             |                                      | JOB NUMBER:  | 22-04             |                |                           |               |                    |  |
| WELL DEPTH:   |      | 15' bgs  |           | BORING<br>Depth:  | 15'bgs                      | 15'bgs REA REPRESED                  |  |                   |                | Patricia Coppolin         | 0             |                    |  |
| DEPTH TO WA   |      |  | NG):      | 8' bgs  |                             | PANY.                                | -+   | Technical Drillin | т Cn           | mnany                     |               |                    |  |
| SCREEN DIAM   |      | 2"   |           | <b>Дертн:</b>   | 15' bgs t                   | to 5' bgs                            |  |                   |                | Sterling, Massach         | s ~~<br>usett | S<br>mpan,         |  |
| SCREEN TYPE/<br>RISER DIAMET  |      |  | ot sch    | edule 40 PV   |                             |                                      | SAMPLING MET   |                   |                | Hollow Stem Aug           |               |                    |  |
| RISER DIAMET  |      | 2"   | 3- 40 1   | <i>Dиртн:</i>   | 5' bgs to                   | 0.6' bgs                             | INT (RP)   | ):                | not measured   |                           |               |                    |  |
|   |      | Schedu   |           |   |                             | <u>.</u>                             |  | ,                 |                |                           |               |                    |  |
| DEPTH   |      | MPLE   |           | XWS/6" AND  | S/                          | AMPLE DESCR                          |  | PIC               | - 1            | WELL                      | LE            | GEND               |  |
| (IN FEET)   | DFL  | TH (FT)  |           | ECOVERY   |                             | AND NOTE:                            | S  | (PPN              | W)             | PROFILE                   |               |                    |  |
| 0   |      | 0-2  |           | (inches)<br>/3/3/4 11"  | <u>Top 11":</u> b           | rown medium SAND                     |  |                   |                | <b>-</b> -1               | œ             | _                  |  |
| 1   |      | -  |           |   |                             |                                      |  | 0,0               | '              |                           |               | Concrete           |  |
| 12  | 2    | 2-4  | 5.        | /3/3/4 14"  | Same as Ab                  | ove                                  |  | 5.9               |                |                           | 14            | Native<br>Material |  |
| 3<br>4  |      |  | <u> </u>  |   | Tom 157 li                  | ght brown medium SAI                 | <b>N</b> (1)   |                   |                |                           |               |                    |  |
| 5   | 4    | <del>1-</del> 6  | 3.        | /3/4/5 15"  | 100 t5 : II                 | gat crown meatum SAI                 | NL   | 34.3              | 3              |                           |               | Bentonite          |  |
| 6   | (    | 5-8  | 3,        | /3/5/4 24"  | Top 22": Sa<br>Bottom: ligh | ame as Above<br>ht brown SAND and SI | T.T  | 312               |                |                           |               | Filter             |  |
| 7   |      |  |           |   |                             |                                      |  |                   |                |                           |               | Sand               |  |
| 8 <u>▼</u><br>9   | 8    | -10  | 2/        | <i>12/2/</i> 2 16"  | <u>Top 16:" lig</u>         | ght brown fine SAND.                 | Wet  | 0,3               |                |                           |               | Riser              |  |
| 10  | 10   | ) <del>-</del> 12  | 2/        | <i>'2/2/2</i> 16"   | Same as abor                | ve grades to a very fir              | ne SAND  | 0.0               |                |                           |               | Screen             |  |
| 11  |      |  |           |   |                             |                                      |  | 0.0               |                |                           |               | Screen             |  |
| 12<br>13  |      |  |           |   |                             |                                      |  |                   |                |                           | ¥             | Water<br>Level     |  |
| 14  |      |  |           |   |                             |                                      |  |                   |                |                           |               |                    |  |
| 15  |      |  |           |   |                             |                                      |  |                   |                |                           |               |                    |  |
| 16  |      |  |           |   | Bottom of B                 | oring. Set well at 15'               |  |                   |                |                           |               |                    |  |
| 17  |      |  |           | !   |                             |                                      |  |                   |                |                           |               |                    |  |
| 19  |      |  |           | ,   |                             |                                      |  |                   |                |                           |               |                    |  |
| 20  |      |  |           |   |                             |                                      |  |                   |                |                           |               |                    |  |
| 21  |      |  |           |   |                             |                                      |  |                   |                |                           |               |                    |  |
| 22  |      |  |           |   |                             |                                      | ļ  |                   |                |                           |               |                    |  |
|   |      |  | _         |   |                             |                                      | 1  |                   |                |                           |               | I                  |  |
| PROPORTIONS US<br>AND 33-50%<br>SOME 20-33%<br>LITTLE 10-20%<br>TRACE 0-10% |      | <2<br>2-4<br>4-8<br>8-15<br>15-30<br>>30   | BLOW C    | COUNT (COHESIVE S<br>VERY SOFT<br>SOFT<br>MEDIUM STIFF<br>STIFF<br>VERY STIFF<br>HARD | sorts)                      | 0-4<br>4-10<br>10-30<br>30-50        | T (GRANULAR SOES<br>VERY LOOSE<br>LOOSE<br>MEDIUM DENSE<br>DENSE<br>VERY DENSE | 5)                | Notes<br>PID a | s:<br>ased: Photovac 2020 |               |                    |  |

|  |                     | œ.E.                                     | ব             |  |                      | BORING /   | WELL ID   | ENTII     | FICATION: M                       | W-2                |
|--|---------------------|--|---------------|--|----------------------|--|---|-----------|-----------------------------------|--------------------|
|  | , <del>- 1</del>    |  |               | 3  |                      |  | SITE NAME:  | Frankl    | Adams School                      |                    |
|  | ر<br>مار می<br>معرب | 70                                       |               | )<br>  |                      |  | SITE LOCATION:  | St. Joh   | nsbury, Vermont                   |                    |
|  |                     | Name of the                              |               | ्र <sup>क्ष</sup><br>श   |                      | INSTA  | ILATION DATE:   | 2 July 2  | 2002                              |                    |
|  | ,                   | Annenia'                                 | 120 p. 100 m. |  |                      | ,  | JOB NUMBER:   | 22-040    |                                   |                    |
| Well Depth:  |                     | 13' bgs                                  | ·             | BORING<br>Depth:   | 13'bgs               |  | REA REPRESEN  | TATIVE:   | Patricia Coppoli                  | <b>1</b> 0         |
| DEPTH TO WAT   |                     |  | NG):          | 7' bgs   |                      |  | Drilling Com  | PANY:     | Technical Drillin                 | ig Company         |
| SCREEN DIAME   |                     | 2"                                       |               | <i>Д</i> кртн:   | 13' bgs to           | 3' bgs   |   |           | Sterling, Massac                  |                    |
| SCREEN TYPE/S  |                     |  | ot sch        | reduie 40 PVC  |                      |  | SAMPLING MET  |           | Hollow Stem Au                    | дег                |
| RISER DIAMET   |                     | 2"                                       | 1 - 121 1     | DEPTH:   | 3' bgs to            | 0.6' bgs   | Reference Po  | INT (RP): | not measured                      |                    |
|  |                     | Schedu                                   | _             |  |                      | B  |   | 515       | 1 386                             | 1                  |
| DEPTH  |                     | MPLE                                     | •             | DWS/6" AND   | SA                   | MPLE DESCR                                       |   | PID       | WELL                              | LEGEND             |
| (IN FEET)  | DEP                 | TH (FT)                                  | ı             | ÉCOVERY  |                      | AND NOTE   | S   | (PPM)     | PROFILE                           |                    |
| 0<br>1   |                     |  |               | (inches)   | ·                    |  |   |           |                                   | Concrete           |
| 2  |                     |  |               |  |                      |  |   |           |                                   | Native<br>Material |
| 3<br>4   |                     | 4-6                                      |               | 3/3/2/3 <i>T</i> "   | Top 7": broy         | wn med SAND. Mois                                | st at bottom  | 50.3      |                                   | Bentonite          |
| 5  |                     |  |               |  |                      |  |   |           |                                   |                    |
| 6  |                     |  |               |  |                      |  |   |           |                                   | Filter<br>Sand     |
| 7<br>8   |                     |  |               |  |                      |  |   |           |                                   | Riser              |
| 8<br>9   | 9                   | -11                                      | 1             | /1/1/2 24"   | <u>Top 24":</u> grej | y fine SAND                                      |   | 151.0     |                                   |                    |
| 10<br>11   |                     |  |               |  |                      |  |   |           |                                   | Screen             |
| 12   |                     |  |               |  |                      |  |   |           |                                   | ₩ Water<br>Level   |
| 13<br>14   |                     |  |               |  | Set well at 13       | ,  | -14-14  |           |                                   |                    |
| 15   |                     |  |               |  |                      |  |   |           |                                   |                    |
| 16   |                     |  |               |  |                      |  |   |           |                                   |                    |
| 17   |                     |  |               |  |                      |  |   |           |                                   |                    |
| 18   |                     |  |               |  |                      |  |   |           |                                   |                    |
| 19   |                     |  |               |  |                      |  |   |           |                                   |                    |
| 20   |                     |  |               |  |                      |  |   |           |                                   |                    |
| 21   |                     |  |               |  |                      |  |   |           |                                   |                    |
| 22   |                     |  |               |  |                      |  |   |           |                                   |                    |
| PROPORTIONS US<br>AND 33-50'<br>SOME 20-33'<br>LITTLE 10-20'<br>TRACE 0-10 | %<br>%<br>%         | <2<br>2-4<br>4-8<br>8-15<br>15-30<br>>30 | BLOW          | COUNT (COHESIVE: VERY SOFT SOFT MEDIUM STIFF STIFF VERY STIFF HARD | SOILS)               | 6LOW COU<br>0-4<br>4-10<br>10-30<br>30-50<br>>50 | NT (GRANULAR SOII<br>VERY LOOSE<br>LOOSE<br>MEDIUM DENSE<br>DENSE<br>VERY DENSE | .5)       | Notes:<br>PED used: Photovno 2020 |                    |

|                               |          | Ç.E                     | · 4.    | -                             |                   | BORING /               | WELL II               | ENT         | IF         | ICATION: M                             | <b>W</b> -3   | 3             |
|-------------------------------|----------|-------------------------|---------|-------------------------------|-------------------|------------------------|-----------------------|-------------|------------|--|---------------|---------------|
|                               | .05      |                         |         | ė.                            |                   |                        | SITE NAME:            |             | _          | dams School                            |               |               |
|                               | (\$<br>T |                         |         |                               |                   |                        | SITE LOCATION:        |             |            | sbury, Verment                         |               | <del></del>   |
| :                             |          | a Alasa                 | giri y  |                               | _                 | INST                   | ALLATION DATE:        | 2 Ju        |            |  |               | <del>-</del>  |
|                               |          | رضاه هنو <sub>ن ا</sub> | W-SO    |                               |                   | ·                      | JOB NUMBER:           | 22-0        |            |  | <del></del> - | <del></del> - |
| WELL DEPTH:                   | ·        | 15' bgs                 |         | BORING<br>DEPTH:              | 15'bg             | 73                     | REA REPRESE           | 1           |            | Patricia Coppolin                      | 0             |               |
| <b>Д</b> БРТН ТО WA           |          | RING DRILL              | ING):   | 8' bgs                        | i                 | <del></del> -          | DRILLING COM          | PANY.       |            | Tophysical D315                        |               | <del>_</del>  |
| SCREEN DIAM                   |          | 2"                      |         | DEPTH:                        | 15' bgs           | to 5' bgs              |                       |             |            | Technical Drillin<br>Sterling, Massach | g COI         | mpany         |
| SCREEN TYPE                   | •        | 0.010 s                 | lot sch | edule 40 PV                   | C                 |                        | Sampling MET          | HOD:        |            | Hollow Stem Aug                        |               | <u> </u>      |
| RISER DIAMET                  |          | 2"                      |         | <i>D</i> ерти:                | 5' bgs to         | o 0.6' bgs             | REFERENCE PO          | INT (RP     | ) <u>:</u> | not measured                           | <u></u>       | <del></del>   |
| RISER TYPE/SI                 |          | Schedu                  |         |                               |                   |                        | ·                     | · · · · · · |            | 200 monsured                           |               |               |
| DEPTH                         |          | MPLE                    | BLC     | WS/6" AND                     | S                 | AMPLE DESCR            | IPTION                | PI          | <u>_</u>   | WELL                                   | 15            | CENO          |
| (IN FEET)                     | DEP.     | TH (FT)                 | R       | ECOVERY                       |                   | AND NOTE               |                       | (PP         |            | PROFILE                                |               | GEND          |
|                               |          |                         | (       | (inches)                      | 1                 |                        | _                     | ( " "       | 141/       | PROFICE                                |               |               |
| 0                             |          |                         | '       | (                             |                   |                        |                       |             |            | _                                      |               |               |
|                               |          |                         | 1       |                               |                   |                        |                       |             |            |  | ▩             | Concrete      |
| 1                             |          |                         |         |                               |                   |                        |                       |             |            | <u>_</u>                               |               |               |
| 2                             |          |                         |         |                               |                   |                        |                       |             |            |  | P             | Native        |
|                               |          |                         | 1       |                               | ļ                 |                        |                       |             |            |  |               | Material      |
| 3                             |          |                         |         |                               |                   |                        |                       |             |            | 18394 183994                           |               |               |
| 3<br>4                        | ,        | 1-6                     | ,       | /3/1/3 9"                     | <u>Top 9":</u> br | own medium SAND.       |                       |             |            | 1888 1888                              |               |               |
| . I                           | _        | <del>-</del> -0         | 3       | 73/1/3 Y                      | ]                 |                        |                       | 43.8        | 8          |  |               | Bentonite     |
| 5                             |          |                         |         |                               |                   |                        | :                     |             |            |  |               |               |
|                               |          |                         |         |                               |                   |                        |                       |             |            |  |               |               |
| 6                             |          | i                       |         |                               |                   |                        |                       |             |            |  | 33357         | Filter        |
| 7                             |          |                         |         |                               |                   |                        |                       |             |            |  |               | Sand          |
| <u>'</u> —                    |          |                         |         |                               |                   |                        |                       |             |            |  |               |               |
| 8                             |          |                         |         |                               |                   |                        |                       |             |            |  | $\Box$        | Diana         |
| 9                             | q.       | -11                     | 2/      | 1/1/1 24"                     | Top 24": Bi       | rown fine SAND. WET    | Speening on           |             |            |  | ш             | Riser         |
|                               | ,        | .                       | 21      | 17171 24                      | water.            |                        |                       | 3.9         |            |  |               |               |
| 10                            |          |                         |         |                               |                   |                        |                       |             |            |  |               | Screen        |
| 11                            |          |                         |         |                               |                   |                        | ĺ                     |             |            |  |               | эстеец        |
|                               |          |                         |         |                               | 1                 |                        |                       |             |            |  |               |               |
| 12                            |          | ļ                       |         |                               | 1                 |                        |                       |             |            |  | •             | Water         |
| 13                            |          | i                       |         |                               |                   |                        |                       |             |            |  | _             | Level         |
|                               |          |                         |         |                               |                   |                        |                       |             |            |  |               |               |
| 14                            |          | ſ                       |         |                               |                   |                        |                       |             |            |  |               |               |
| 15                            |          | İ                       |         |                               | }                 |                        | İ                     |             | ĺ          |  |               |               |
|                               |          | .                       |         |                               | D-11 2***         |                        |                       |             |            |  |               |               |
| 16                            |          |                         |         |                               | isottom of B      | oring. Set well at 15' |                       |             | ļ          |  |               | i             |
| 17                            |          |                         |         |                               |                   |                        |                       |             |            | 60000000000000000000000000000000000000 |               |               |
| 18                            |          |                         |         |                               |                   |                        | ļ                     |             | Į          |  |               |               |
| <del></del>                   |          | İ                       |         |                               |                   |                        |                       |             |            |  |               |               |
| 19                            |          | -                       |         |                               |                   |                        |                       |             |            |  |               |               |
| 20                            |          |                         |         |                               |                   |                        | j                     |             |            |  |               |               |
|                               |          | j                       |         | ĺ                             |                   |                        | 1                     |             |            |  |               |               |
| 21                            |          | Ī                       |         |                               |                   |                        |                       |             |            |  |               |               |
| 22                            |          |                         |         |                               |                   |                        |                       |             | j          | 1                                      |               | 1             |
|                               |          | <u> </u>                |         |                               |                   |                        |                       |             | 1          |  |               |               |
| PROPORTIONS USE<br>AND 33-50% | ED       | <2 E                    | SLOW CO | DUNT (COHESIVE :<br>VERY SOFT | SOILS)            |                        | (GRANULAR SOILS       | )           | Note       | <b>S</b> :                             |               |               |
| SOME 20-33%<br>LITTLE 10-20%  |          | 2-4<br>4-8              |         | SOFT                          |                   | 4-10                   | VERY LOOSE<br>LOOSE   |             | PID        | used: Photovac 2020                    |               | ŀ             |
| TRACE 0-10%                   |          | 8-15                    |         | MEDIUM STIFF<br>STIFF         |                   |                        | MEDIŲM DENSE<br>DENSE |             |            |  |               |               |
| ····                          |          | 15-30<br>>30            |         | VERY STIFF<br>HARD            |                   | i                      | VERY DENSE            |             |            |  |               | ŀ             |

|                       |                         |                       |            | E.,          | ⊲1    |                                | В                    | ORING/                                | WELL ID                        | ENTIF     | ICATION: N              | 1W-4   | . [       |
|-----------------------|-------------------------|-----------------------|------------|--------------|-------|--------------------------------|----------------------|---------------------------------------|--------------------------------|-----------|-------------------------|--|-----------|
|                       |                         |                       |            |              |       |                                |                      |                                       | SITE NAME:                     | Frank A   | dams School             |  |           |
|                       |                         | 2.75<br>0.75<br>77.13 |            |              |       | 요<br>문                         | · <del>-</del>       |                                       | SITE LOCATION:                 | L         | sbury, Vermont          |  |           |
|                       |                         | 7117                  |            |              |       | িছ<br>ক                        | _                    |                                       | LLATION DATE:                  | 2 July 2  |                         |  |           |
|                       |                         | î                     | 3. Marie   |              | "'    | _                              | -                    |                                       | JOB NUMBER:                    | 22-040    |                         |  |           |
| Well Dept             | <i>H:</i>               |                       | 15'        | bgs          | ·     | BORING                         | 15'bgs               |                                       | RRA REPRESEN                   |           | Patricia Coppo          | lino   |           |
| <b>Дертн</b> то И     | T/ 1em                  | on for                | 727.157.11 | LIGHT INT    |       | <i>Dертн:</i><br><b>8' bgs</b> |                      | · · · · · · · · · · · · · · · · · · · | Drilling Com                   | PANT:     | Technical Dril          | ing Co   | mpany     |
| SCREEN DIA            |                         |                       | 2"         | KILIIN       | 3).   | Depth:                         | 15' bgs to :         | 5° hes                                |                                | ••        | Sterling, Massa         |  |           |
| SCREEN TYP            |                         |                       |            | 10 do        | t sch | edule 40 PV                    |                      |                                       | SAMPLING MET                   | HOD:      | Hollow Stem A           |  |           |
| RISER DIAM            |                         |                       | 2"         |              | 1     | DEPTH:                         | 5' bgs to 0.         | 6' bgs                                | Reference Po                   | INT (RP): | not measured            |  |           |
| RISER TIPE            | /Siz                    | E.                    | Sch        | edul         | 40 I  | PVC                            |                      |                                       |                                |           |                         |  |           |
| DEPTH                 | T                       | S/                    | MPL        | E            | BLC   | WS/6" AND                      | SAN                  | IPLE DESCR                            | IPTION                         | PID       | WELL                    | LE   | GEND      |
| (IN FEET              | - 1                     | DEF                   | TH (       | =T)          | Ri    | ECOVERY                        |                      | AND NOTE                              | S                              | (PPM)     | PROFILE                 |  |           |
| <b>\</b> ****         | 1                       |                       | `          | 1            |       | (inches)                       |                      |                                       |                                |           |                         | -  |           |
| 0                     |                         |                       |            | ]            |       | ,                              |                      |                                       |                                |           |                         |  | Concrete  |
| 1                     |                         |                       |            |              |       |                                |                      |                                       |                                | 1         |                         |  | ' [       |
| 1                     |                         |                       |            |              |       |                                |                      |                                       |                                |           |                         | 77 <del>-</del>                                | Native    |
| 2                     |                         |                       |            |              |       |                                |                      |                                       |                                | ]         |                         |  | Material  |
| 3                     |                         |                       |            | ]            |       |                                |                      |                                       |                                |           |                         |  |           |
| 4                     |                         |                       | 4-6        |              | 2     | 2/5/4/5 19"                    | <u>Top 19</u> ": bms | wn medium SAND.                       | Moist at bottom.               | 0.0       |                         |  | Bentonite |
| 5                     |                         |                       |            | Ì            |       |                                |                      |                                       |                                |           |                         |  |           |
| <i></i>               |                         |                       |            |              |       |                                |                      |                                       |                                |           |                         |  | Filter    |
| 6                     |                         |                       |            |              |       |                                |                      |                                       |                                |           |                         |  | Sand      |
| 6<br>7<br>8_ <b>_</b> |                         |                       |            |              |       |                                |                      |                                       |                                |           |                         | <b>// // // // // // // // // // // // // </b> | Riser     |
| 8                     |                         |                       |            |              | •     | 1044/2 162                     | <u>Top 16".</u> Sam  | e as above. WET                       |                                | 0.0       |                         |  | ] 10301   |
| 9                     |                         |                       | 9-11       |              | 3     | 3/2/4/3 16°°                   |                      |                                       |                                | 0.0       |                         |  | Screen    |
| 10                    |                         |                       |            |              |       |                                |                      |                                       |                                |           |                         |  | 3 50.000  |
| 11<br>12              |                         |                       |            |              |       |                                |                      |                                       |                                |           |                         | <b>/// y</b>                                   | Water     |
|                       | ı                       |                       |            |              |       |                                |                      |                                       |                                |           |                         |  | - Levei   |
| 13                    |                         |                       |            |              |       |                                |                      |                                       |                                |           |                         |  |           |
| 14                    |                         |                       |            | :            |       |                                |                      |                                       |                                |           |                         |  |           |
| 15                    |                         |                       |            |              |       |                                | Bottom of Bo         | uing. Set well at 15                  | <del></del>                    | -         |                         |  |           |
| 16                    |                         |                       |            |              |       |                                | Zajanii Oi IIO       |                                       |                                |           | Company Com             | 370  |           |
| 17                    |                         |                       |            |              |       |                                |                      |                                       |                                |           |                         |  |           |
| 18                    |                         |                       |            |              |       |                                |                      |                                       |                                |           |                         | 1  |           |
| 19                    |                         |                       |            |              |       |                                |                      |                                       |                                |           |                         |  |           |
| 20                    |                         |                       |            |              |       |                                |                      |                                       |                                |           |                         |  |           |
| 21                    |                         |                       |            |              |       |                                |                      |                                       |                                |           |                         |  |           |
| 22                    |                         |                       |            |              |       |                                |                      |                                       |                                | <u> </u>  |                         |  |           |
| PROPORTIO             |                         |                       |            | <2           | BLOW  | COUNT (COHESIV                 | E SOILS)             | 8LOW CC                               | ÜNT (GRANULAR SO<br>VERY LOOSE | DILS)     | Notes:                  | -  |           |
| SOME 2                | 39-50<br>20-33<br>40-30 | 76                    |            | 2-4<br>4-8   |       | SOFT<br>MEDIUM STIFF           | •                    | 4-10<br>10-30                         | LOOSE<br>MEDIUM DENSE          | <u> </u>  | PID used: Photovau 2020 |  |           |
| LITTLE 1<br>TRACE     | 10-20<br>0-10           |                       |            | 8-15         |       | STIFF                          |                      | 30-50                                 | DENSE                          |           |                         |  |           |
|                       |                         |                       |            | 15-30<br>>30 |       | VERY STIFF<br>HARD             |                      | >50                                   | VERY DENSE                     |           |                         |  |           |

Ross Environmental Associates Phone: 802-253-4280 73 School Street PO Box 1533

Stowe, Verment 05672 Fax: 802-253-4829 A
P
P
P
E
LABORATORY
ANALYTICAL REPORTS

D
I
X

D



# **Laboratory Services**

160 James Brown Drive Williston, Vermont 05495 (802) 879-4333 FAX 879-7103

# LABORATORY REPORT

CLIENT: Ross Environ. Assoc., Inc.

PROJECT: Frank School/22-040

REPORT DATE: July 23, 2002

ORDER ID: 18662

DATE RECEIVED: July 11, 2002

SAMPLER: JS

| Site: MW-1<br>Ref. Number; 195394<br>Anal. Method: SW 8021B<br>Date Sampled: 7/10/02<br>Time Sampled: 1:10 PM<br>Analysis Date: 7/19/02<br>Analyst: 420 |                  | Site: MW-3 Ret. Number: 196396 Anal. Method: SW 8021B Date Sampled: 7/10/02 Time Sampled: 1:30 PM Analysis Date: 7/19/02 Analysis: 420 |              | Site: MW-22 Ref. Number: 196398 Anal. Method: SW 8021B Date Sampled: 7/10/02 Time Sampled: NI Analysis Date: 7/19/02 Analyst: 420     |              |
|---|------------------|--|--------------|---|--------------|
| <u>Parameter</u>  | Results ug/L     | <u>Parameter</u>   | Results ug/L | Parameter Parameter   | Results ug/L |
| MTBE  | < 10.0           | MTBE   | < 2.0        | MTBE  | < 10.0       |
| Benzene   | < 5.0            | Benzene  | < 1.0        | Benzene   | < 5.0        |
| Toluene   | 13.9             | Toluene  | < 1.0        | Toluene   | < 5.0        |
| Ethylbenzene  | < 5.0            | Ethylbenzene   | < 1.0        | Ethylbenzene  | < 5.0        |
| Xylenes, Total  | 46.7             | Xylenes, Total   | < 2.0        | Xylenes, Total  | 15.3         |
| 1,3,5 Trimethyl Benzene   | 17.4             | 1.3,5 Trimethyl Benzene  | < 1.0        | 1,3,5 Trimethyl Benzene   | 17.8         |
| 1,2,4 Trimethyl Benzenc   | 30. <del>6</del> | 1,2,4 Trimethyl Benzene  | < 1.0        | 1,2,4 Trimethyl Benzene   | 52.3         |
| Naphtholene   | 35.5             | Naphthalene  | < 1.0        | Naphthalene   | 124.         |
| UIP's   | > 10             | UIP's  | > 10.        | U!P's   | > 10.        |
| Surrogate 1   | 102.%            | Surrogate 1  | 101.%        | Surrogate 1   | 100.%        |
| Site: MW-2<br>Ref. Number: 196395<br>Anal. Method: SW 8021B<br>Date Sampled: 7/10/02<br>Time Sampled: 1:20 PM<br>Analysis Date: 7/19/02<br>Analyst: 420 |                  | Site: MW-4 Ref. Number: 196397 Anal. Method: SW 8021B Date Sampled: 7/10/02 Time Sampled: 1:40 PM Analysis Date: 7/18/02 Analyst: 420  |              | Site: TB-1 Ref. Number: 196399 Anal. Method: SW 8021B Date Sampled: 7/10/02 Time Sampled: 1:00 PM Analysis Date; 7/18/02 Analyst: 420 |              |
| <u>Parameter</u>  | Results ug/L     | <u>Parameter</u>   | Results ug/L | Parameter   | Results ug/L |
| МТВЕ  | < 16.0           | MTDE   | < 2.0        | MTBE  | < 2.0        |
| Benzenc   | < 5.0            | Велгене  | < 1.0        | Benzene   | < 1.0        |
| Toluene   | < 5.0            | Toluene  | < 1.0        | Toluene   | < 1.0        |
| Ethylbenzene  | < 5.0            | Ethylbenzene   | < 1.0        | Ethylbenzene  | < 1.0        |
| Xylenes, Total  | 14.7             | Xylenes, Total   | < 2.0        | Xylenes, Total  | < 2.0        |
| 1,3,5 Trimethyl Benzene   | 16.6             | 1,3,5 Trimethyl Benzene  | < 1.0        | 1,3,5 Trimethyl Benzene   | < 1.0        |
| 1,2,4 Trimethyl Benzene   | 48.8             | 1,2,4 Trimethyl Benzenc  | < 1.0        | 1,2,4 Trimethyl Benzene   | < 1.0        |
| Naphthalene   | 124.             | Naphthalene  | < 1.0        | Naphthalene   | < 1.0        |
| UIP's   | > 10.            | UlP's  | 0.           | UIP's   | 0.           |
| Surrogate 1   | 100.%            | Surrogate 1  | 100.%        | Surrogate 1   | 102.%        |



# **Laboratory Services**

160 James Brown Drive Williston, Vermont 05495 (802) 879-4333 FAX 879-7103

# LABORATORY REPORT

CLIENT: Ross Environ. Assoc., Inc.

PROJECT: Frank School/22-040

REPORT DATE: July 18, 2002

ORDER ID: 18662

DATE RECEIVED: July 11, 2002

SAMPLER: JS

ANALYST: 333

| Ref. Number: 196394 | Site: MW-1    |             | Date Sampled: July 10, 2002 | Time: 1:10 PM |
|---------------------|---------------|-------------|-----------------------------|---------------|
| <u>Parameter</u>    | <u>Result</u> | <u>Unit</u> | Method                      | Analysis Date |
| TPH 8015 DRO        | 7.63          | mg/L        | SW 8015B                    | 7/17/02       |
| Ref. Number: 196395 | Site: MW-2    |             | Date Sampled: July 10, 2002 | Time: 1:20 PM |
| <u>Parameter</u>    | Result        | <u>Unit</u> | Method                      | Analysis Date |
| TPH 8015 DRO        | 9.09          | mg/L        | SW 8015B                    | 7/17/02       |
| Ref. Number: 196396 | Site: MW-3    |             | Date Sampled: July 10, 2002 | Time: 1:30 PM |
| <u>Parameter</u>    | Result        | <u>Unit</u> | Method                      | Analysis Date |
| TPH 8015 DRO        | 0.66          | mg/L        | SW 8015B                    | 7/18/02       |
| Ref. Number: 196397 | Site: MW-4    |             | Date Sampled: July 10, 2002 | Time: 1:40 PM |
| <u>Parameter</u>    | Result        | <u>Unit</u> | <u>Method</u>               | Analysis Date |
| TPH 8015 DRO        | < 0.40        | mg/L        | SW 8015B                    | 7/18/02       |
| Ref. Number: 196398 | Site: MW-22   |             | Date Sampled: July 10, 2002 | Time; NI      |
| <u>Parameter</u>    | Result        | <u>Unit</u> | Method                      | Analysis Date |
| TPH 8015 DRO        | 8.54          | mg/L        | SW 8015B                    | 7/18/02       |